



UNITED STATES CONSUMER PRODUCT SAFETY COMMISSION

Recall Releases

Important Product Safety Recall Information

Research Products Recalls Steam Humidifiers Due to Fire Hazard



Name of Product: STEAM HUMIDIFIERS

Distributed between 2010 and Jan, 2015

Aprilaire Model #s 800, 801, 865, 866

Carrier, Bryant #s HUMXXSTM3034

York, Coleman, Luxaire #s S1-STEAM 8000TO1

Hazard: The recalled steam humidifiers contain a specific type of electrode wire with a “D” shaped connector that can loosen causing arcing and/or overheating, posing a fire hazard to consumers.

Remedy: Consumers should immediately stop using and shut off the recalled humidifiers and contact Research Products to receive a free electrode wire repair kit and assistance with identifying a qualified contractor to schedule an appointment for a free replacement of their electrode connector wires.

Qualified contractors participating in the repair will be offered a labor allowance by Research Products.

Research Products contact for more information: www.rpcrecall.com/steamhumidifier , or 1-888-742-2401

6-23-23